

SECTION V - HEALTH HAZARD DATA

Effects of Overexposure: Short term, fumes may irritate eyes or respiratory system
 Long term, may affect pulmonary function and/or may cause metal fume fever.
 Emergency & First Aid Procedures: Remove to fresh air, call physician.

Carcinogenicity: NTP -No; IARC -No; OSHA -No.

SECTION VI - REACTIVITY DATA

Stability	Unstable		Conditions to Avoid
	Stable	X	
Incompatibility (Materials to Avoid): NONE			
Hazardous Decomposition Products:			
Hazardous Polymerization: NOT APPLICABLE			

SECTION VII - SPILL OR LEAK PROCEDURES

NOT APPLICABLE

SECTION VIII - SPECIAL PROTECTION INFORMATION (See Note)

Respiratory Protection (specify type) Weld Fume Respirator or Airline Respirator for confined space or where exposures are above TLV.

Ventilation:

Local Exhaust: Yes, in confined spaces

Mechanical (general): Yes, where exposures exceed TLV

Eye Protection: Colored Adsorptive Lens No. to Safety glasses.

Protective Gloves: Welder's Protective Gloves

Other Protective Equipment: Protective Clothing - Leather Apron

SECTION IX - SPECIAL PRECAUTIONS (See Note)

Other Precautions: Arc & Sparks could be source of ignition of combustible products.

NOTE: Reference is directed, without endorsement or recommendation, to the ANSI Standard Safety in Welding & Cutting Z49.1-1973 (American Welding Society Publication Z49.1-1973).