

Revised
March 25, 1987

LENOX Band-Ade™ Machine Cleaner

MATERIAL SAFETY DATA SHEET

SECTION I

MANUFACTURER'S NAME American Saw & Mfg. Company (S.I.C.)		EMERGENCY TELEPHONE NO. (413) 525-3961
ADDRESS (Number, Street, City, State and ZIP Code) 301 Chestnut St., East Longmeadow, MA 01028		
CHEMICAL NAME AND SYNONYMS A cleaner		TRADE NAME AND SYNONYMS LENOX BAND-ADE™ MACHINE CLEANER
CHEMICAL FAMILY N/A	FORMULA Proprietary	

SECTION II - HAZARDOUS INGREDIENTS

PAINTS, PRESERVATIVES & SOLVENTS	%	TLV (Units)	ALLOYS AND METALLIC COATINGS	%	TLV (Units)
PIGMENTS	0		BASE METAL	0	
CATALYST	0		ALLOYS	0	
VEHICLE	0		METALLIC COATINGS	0	
SOLVENTS	0		FILLER METAL PLUS COATING OR CORE FLUX	0	
ADDITIVES	0		OTHERS	0	
OTHERS	0				
HAZARDOUS MIXTURES OF OTHER LIQUIDS, SOLIDS, OR GASES				%	TLV (Units)
Does not contain any ingredients on the EPA Priority Pollutants list.					

SECTION III - PHYSICAL DATA

BOILING POINT (°F.)	216°F	SPECIFIC GRAVITY (H₂O=1)	1.14
VAPOR PRESSURE (mm Hg.)	N/A	PERCENT, VOLATILE BY VOLUME (%)	N/A
VAPOR DENSITY (AIR=1)	N/A	EVAPORATION RATE (=1)	N/A
SOLUBILITY IN WATER	Complete		
APPEARANCE AND ODOR	Light yellow, no odor		

SECTION IV - FIRE AND EXPLOSION HAZARD DATA

FLASH POINT (Method used)	None (COC)	FLAMMABLE LIMITS	Lel	Uel
EXTINGUISHING MEDIA	N/A This material is not combustible.			
SPECIAL FIRE FIGHTING PROCEDURES				
Avoid excessive contact with skin or eyes (See Section V)				
UNUSUAL FIRE AND EXPLOSION HAZARDS				
None				

SECTION V - HEALTH HAZARD DATA	
THRESHOLD LIMIT VALUE	None established
EFFECTS OF OVEREXPOSURE	Slight skin irritation to some individuals.
EMERGENCY AND FIRST AID PROCEDURES	
	Eye Contact - Flush with water and as a precaution, see a physician.
	Skin Contact - Wash with soap and water. Change soaked clothing for comfort.
	See a physician, should individual so desire, as a precautionary measure.

SECTION VI - REACTIVITY DATA			
STABILITY	UNSTABLE		CONDITIONS TO AVOID
	STABLE	X	
INCOMPATIBILITY (<i>Materials to avoid</i>) Strong acids and strong bases.			
HAZARDOUS DECOMPOSITION PRODUCTS			
HAZARDOUS POLYMERIZATION	MAY OCCUR		CONDITIONS TO AVOID
	WILL NOT OCCUR	X	

SECTION VII - SPILL OR LEAK PROCEDURES	
STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED	
Small amounts, flush with water. Large amounts should be absorbed with suitable material and disposed of in accordance with local, state and federal regulations.	
WASTE DISPOSAL METHOD	
Material is biodegradable.	

SECTION VIII - SPECIAL PROTECTION INFORMATION			
RESPIRATORY PROTECTION (<i>Specify type</i>)		None needed	
VENTILATION	LOCAL EXHAUST	Not needed	SPECIAL
	MECHANICAL (<i>General</i>)	Normal ventilation	OTHER
PROTECTIVE GLOVES	Not needed (See Section IX)	EYE PROTECTION	Approved safety glasses as required by employer.
OTHER PROTECTIVE EQUIPMENT			

SECTION IX - SPECIAL PRECAUTIONS	
PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING	
Avoid freezing.	
OTHER PRECAUTIONS	Those sensitive to skin irritation may wish to consult their safety director or physician for appropriate protective measures.