

MATERIAL SAFETY DATA SHEET

Required under USDL Safety and Health Regulations for Ship Repairing,
Shipbuilding, and Shipbreaking (29 CFR 1915, 1916, 1917)

SECTION I

MANUFACTURER'S NAME THERMACOTE WELCO		EMERGENCY TELEPHONE NO. 704-739-6421
ADDRESS HWY 161, YORK ROAD, KINGS MOUNTAIN, N.C. 28086		
CHEMICAL NAME AND SYNONYMS		TRADE NAME AND SYNONYMS 3-FH
CHEMICAL FAMILY	FORMULA	

SECTION II HAZARDOUS INGREDIENTS

	OTHER	WT.	TLV (units) mg/m ³
	Mn.	0.5	05
	Cr.	1.0	1.0
	Fe as FeO	98.0	10.0
	C	0.5	15.0

The term "hazardous" should be interpreted as a term required and defined in the OSHA Hazard Communications Standard (29CFR 1910.1200) and does not necessarily imply the existence of any hazard.

SECTION III - PHYSICAL DATA

BOILING POINT (°F.) N/A	SPECIFIC GRAVITY (H ₂ O=1)
VAPOR PRESSURE (mm Hg.)	PERCENT VOLATILE BY VOLUME (%)
VAPOR DENSITY (AIR=1)	EVAPORATION RATE (_____ = 1)
SOLUBILITY IN WATER	
APPEARANCE AND ODOR	

SECTION IV - FIRE AND EXPLOSION HAZARD DATA

FLASH POINT (Method used) N/A	FLAMMABLE LIMITS	UEL	UEL
EXTINGUISHING MEDIA			
SPECIAL FIRE FIGHTING PROCEDURES			
UNUSUAL FIRE AND EXPLOSION HAZARDS			

SECTION V HEALTH HAZARD DATA

EFFECTS OF OVEREXPOSURE	EMERGENCY AND FIRST AID PROCEDURES
pulmonary irritation from dust inhalation	remove to fresh air

SECTION VI REACTIVITY DATA

STABILITY	UNSTABLE	
	STABLE	X
INCOMPATIBILITY (MATERIALS TO AVOID)		None
HAZARDOUS DECOMPOSITION PRODUCTS		
CO, CO ₂ , Ozone, oxides of nitrogen		
HAZARDOUS POLYMERIZATION		Not Applicable

SECTION VII SPILL OR LEAK PROCEDURES

Not Applicable

SECTION VIII SPECIAL PROTECTION INFORMATION (See Note)

RESPIRATORY PROTECTION (SPECIFY TYPE)	
Weld fume respirator or airline respirator for confined space or where exposures are above TLV.	
VENTILATION	LOCAL EXHAUST in semi-open or poorly ventilated spaces
	MECHANICAL (GENERAL) in semi-open or poorly naturally ventilated space
EYE PROTECTION Face shield and safety glass #12 shade	
PROTECTIVE GLOVES Welder's protective gloves	
OTHER PROTECTIVE EQUIPMENT Welder's clothing for protection against sparks and hot material	

SECTION IX SPECIAL PRECAUTIONS (See Note)

OTHER PRECAUTIONS Arc and sparks could be source of ignition of combustible products

NOTE: For additional information, see American National Standard Safety in Welding and Cutting Z49.1-1967 (American Welding Society Publication Z49.1-1967).