

LENOX Band-Ade™ Sawing Fluid

Revised
November 3, 1986

MATERIAL SAFETY DATA SHEET

SECTION I			
MANUFACTURER'S NAME American Saw & Mfg. Company (S.I.C.)		EMERGENCY TELEPHONE NO. (413) 525-3961	
ADDRESS (Number, Street, City, State and ZIP Code) 301 Chestnut St., East Longmeadow, MA 01028			
CHEMICAL NAME AND SYNONYMS A sawing fluid		TRADE NAME AND SYNONYMS LENOX BAND-ADE™	
CHEMICAL FAMILY N/A		FORMULA Proprietary	

SECTION II - HAZARDOUS INGREDIENTS					
PAINTS, PRESERVATIVES & SOLVENTS	%	TLV (Units)	ALLOYS AND METALLIC COATINGS	%	TLV (Units)
PIGMENTS	0		BASE METAL	0	
CATALYST	0		ALLOYS	0	
VEHICLE	0		METALLIC COATINGS	0	
SOLVENTS	0		FILLER METAL PLUS COATING OR CORE FLUX	0	
ADDITIVES	0		OTHERS	0	
OTHERS	0				
HAZARDOUS MIXTURES OF OTHER LIQUIDS, SOLIDS, OR GASES				%	TLV (Units)
This product does not contain any ingredient set forth by the Occupational Safety and					
Health Administration or by the Environmental Protection Agency on their list of hazardous chemicals.					

SECTION III - PHYSICAL DATA			
BOILING POINT (°F.)	218°F	SPECIFIC GRAVITY (H ₂ O=1)	1.29
VAPOR PRESSURE (mm Hg.)	N/A	PERCENT, VOLATILE BY VOLUME (%)	N/A
VAPOR DENSITY (AIR=1)	N/A	EVAPORATION RATE (_____=1)	N/A
SOLUBILITY IN WATER	Complete		
APPEARANCE AND ODOR	Amber, little odor.		

SECTION IV - FIRE AND EXPLOSION HAZARD DATA							
FLASH POINT (Method used)	None (COC)	FLAMMABLE LIMITS	<table border="1"> <tr> <td>LeI</td> <td>UeI</td> </tr> <tr> <td></td> <td></td> </tr> </table>	LeI	UeI		
LeI	UeI						
EXTINGUISHING MEDIA	Water, Co ₂ , dry powder						
SPECIAL FIRE FIGHTING PROCEDURES							
Avoid excessive contact with skin or eyes.							
UNUSUAL FIRE AND EXPLOSION HAZARDS							
None							

SECTION V - HEALTH HAZARD DATA

THRESHOLD LIMIT VALUE None established

EFFECTS OF OVEREXPOSURE None

EMERGENCY AND FIRST AID PROCEDURES

Wash eyes with water. Wash skin with soap and water. Soaked clothing should be changed.

See a physician should individual so desire as a precautionary measure.

SECTION VI - REACTIVITY DATA

STABILITY	UNSTABLE		CONDITIONS TO AVOID
	STABLE	X	

INCOMPATIBILITY (*Materials to avoid*) Strong acids and bases

HAZARDOUS DECOMPOSITION PRODUCTS

HAZARDOUS POLYMERIZATION	MAY OCCUR		CONDITIONS TO AVOID
	WILL NOT OCCUR	X	

SECTION VII - SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED

Small amounts, flush with water. Large amounts should be absorbed with suitable material
and disposed of in accordance with local, state and federal laws.

WASTE DISPOSAL METHOD

Material is biodegradeable.

SECTION VIII - SPECIAL PROTECTION INFORMATION

RESPIRATORY PROTECTION (*Specify type*) None needed

VENTILATION	LOCAL EXHAUST	Not needed	SPECIAL
	MECHANICAL (<i>General</i>)	Normal ventilation	OTHER

PROTECTIVE GLOVES Rubber EYE PROTECTION Approved goggles

OTHER PROTECTIVE EQUIPMENT

SECTION IX - SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING

Avoid freezing

OTHER PRECAUTIONS